



Tel: 0151 357 1901

Web: [www.mrhydraulics.co.uk](http://www.mrhydraulics.co.uk)



## White Grease or Water in Hydraulic Oil?

The white grease appearance on the underside of this filler cap is not grease but a classic sign of water contaminated hydraulic oil & its removal is vital before irreversible damage is done, leading to expensive machine repairs.



The hydraulic filler tank on this Cat Excavator had an unexpected ingress of water which emulsified the oil & rendered the equipment useless and the job stopped.





Tel: 0151 357 1901

Web: [www.mrhydraulics.co.uk](http://www.mrhydraulics.co.uk)



**Our client endured several production days lost, unnecessary actions to try and resolve & multiple drums of hydraulic oil wasted before M&R Hydraulics got the call for help.**

**In this instance, a Hy-Pro Filtration mobile Vacuum Dehydrator was deployed to remove the emulsified water from the hydraulic oil. Within 48hrs, the hydraulic oil was transformed into its original clean & dry condition.**

**So, if you encounter a mayo like substance or notice a milky appearance to your hydraulic oil, don't delay in reaching out to M&R Hydraulics for assistance & avoid the unnecessary oil wastage or worse still, mechanical failures related to water in hydraulic oil.**

